


Model 1600 - 1350 Watt/12.27 Amp/110 V



Model 110 V

Pos. No.	Part- No.	Item No.	Designation	Pos. No.	Part- No.	Item No.	Designation
003	4931618253	52003-3	Screw	201	4931912093	52201	Needle bearing
004	4931624171	52004-2	Cable (4 m) 110 V	204	4931368037	52204	Ball bearing
100	4931378464	52100-3	Motor-plastic case	205	4931622761	52205	Washer
101	4931378134	52101-3	Service case cover	206	4931616614	52206	Locking ring
105	4931393896	52105-2	Magnetic field 110 V	207	4931326929	52207	Locking pin
106	4931409583	52106-2	Armature with pinion 110 V	208	4931326942	52208	Compressing spring
107	4931341088	52107	Fan	209	4931326930	52209	Push button
108	4931624360	52108	Ball bearing	210	4931317532	52210	Screw
110	4931271823	52110	Sealing ring	211	4931254894	52211	Spacer
113	4931307147	52113	Magnetic ring	212	4931369783	52212	spindle shaft
116	4931378135	52116-3	Flange	213	4931385801	52213	Bearing shield
117	4931271824	52117	Spacer ring	214	4931362949	52214-3	Spacer ring
120	4931382268	52120-3	Carbon brush holder	215	4931407579	52215-3	Crown wheel
127	4931378619	52127-2	Electronic-unit 110 V	217	4931622009	52217	Sealing ring
128	4931623738	52128	Cable	230	4931362085	52230	Washer
129	4931326953	52129	Bearing cover	231	4931378280	52231-3	Nut
131	4931392592	52131-1	Carbon brush 110 V	701	4931369805	52700	hand grip with foam
133	4931378146	52133-3	Ergo-grip	702	4931403100	52702	Protection cover
135	4931378983	52135-3	Switch	703	4931403101	52706	Polycarbonat extension
147	4931618253	52003-3	Screw	704	4931403102	65208	knurled screw
149	4931623591	52149-3	Screw	705	4931403103	50048	Screw for spindle shaft
160	4931364242	52160-2	Cable connection 110 V	706		52710	variable hand grip (complete)
200	4931412273	52200-3	Gear box				